




**Extent of realized geological works:**

- geophysical measurements
- exploratory non-equipped boreholes (Geoprobe probes) - 50 pcs
- equipped monitoring boreholes - 18 pcs
- hydrodynamic tests
- sampling work and field measurements
- laboratory work
- drawing up a final report with a risk analysis
- drawing up a feasibility study of remediation



Customer:



Ministry of Environment of the Slovak Republic  
 Námestie Ľ. Štúra 1  
 812 35 Bratislava

Contractor of geological works:

Group  
 of suppliers  
 - EB SURVEY




EKOHYDROGEO  
 ŽITNÝ



## Geological Survey Results:

- in total 15 pollutants were detected in the evaluated area, respectively pollution indicators
- the dominant pollutants are chlorinated aliphatic hydrocarbons: 1,1,2,2-tetrachloroethene (PCE), 1,1,2-trichloroethene (TCE), cis 1,2-dichloroethene (DCE)
- performed risk analysis of the contaminated area demonstrated the presence of environmental risk from groundwater pollution (TCE, DCE)
- performed risk analysis confirmed the health risk for individual residents of Albertov dvor
- environmental remediation has been recommended
- a complex of suitable remediation methods has been proposed



Budget of the geological task: **196 195 €** (excluding VAT)

Solution time: **5/2015 - 10/2015**



**ENVIGEO, Inc.** Kynceľovská cesta 2/8, 974 11 Banská Bystrica

tel.: +421 (48) - 471 24 30 mail: [envigeo@envigeo.sk](mailto:envigeo@envigeo.sk)  
 fax: +421 (48) - 471 24 23 web: [www.envigeo.eu](http://www.envigeo.eu)